DESKSTOR
deskstor.co.uk

CHECKLIST

Desk strength checklist for heavy equipment

- [ ] Measure combined weight of all equipment you plan to place on the desk
- [ ] Choose a desk rated for fifty percent more than your measured total
- [ ] Inspect frame for welded steel and box-section legs
- [ ] Check desktop thickness is at least eighteen millimetres
- [ ] Confirm a cross-brace runs beneath the full width of the surface
- [ ] Count legs: desks over 1,200 millimetres wide need five supports or a pedestal
- [ ] Test stability by pressing corners and pushing the frame sideways
- [ ] Locate existing cable grommets to avoid drilling new holes
- [ ] Plan equipment placement to distribute weight evenly across the surface
- [ ] Tighten all fixings evenly after assembly is complete