CHECKLIST

Mobile pedestal selection checklist

- [ ] Measure desk clearance from floor to underside of worktop, subtract twenty millimetres
- [ ] List items to store and estimate total weight per drawer
- [ ] Confirm castor material suits your floor type without causing marks or gathering debris
- [ ] Test lock and brake with drawers loaded, checking for tipping and creep
- [ ] Choose steel construction if drawer loads exceed twelve kilograms or unit will move daily
- [ ] Verify drawer runners are ball-bearing if pedestal will see heavy or frequent use
- [ ] Label spare keys and store one off-site to avoid replacement delays
- [ ] Plan maintenance schedule for castor cleaning and lock lubrication every few months